

Street no.	Street name	Condition	Works required
189	Allingham	Dieback/dying	Removal
191	Allingham	Dieback/dying	Removal
11	Balblair	Dieback/ complaints resident	Removal
40A	Barney	Priority noxious weed	Removal
40A	Barney	Priority noxious weed	Removal
40A	Barney	Priority noxious weed	Removal
1	Barry	Dead	Remove broken branches
3	Barry	Dead	Removal
318	Beardy	Dying	Removal
312	Beardy	Dying	Removal
80	Beardy	Dying	Removal
82	Beardy	Dying	Removal
27	Bishop Crescent	Deadwood/ Dying	Removal
37	Bishop Crescent	Rot and fungal growth in trunk	Removal
19	Bishop Crescent	Deadwood	prune/deadwood
18	Bishop Crescent	Dead	Removal
100	Butler	Dying	Removal
108	Butler	Dying	Removal
116	Butler	Dying	Removal
118	Butler	Dead	Removal
23	Canambe	Deadwood/dying	Removal
225	Chapel	Deadwood/ branch loading	Prune/deadwood
1	Chestnut	Dead	Removal
	Cnr Erskine & Centennial	Deadwood/ branch loading	Removal
	Cnr Erskine & Centennial	Deadwood/ branch loading	Removal
4	Dalton	Dying	Removal
20	Dalton	Dead	Removal
153	Donnelly	Priority noxious weed	Removal
153	Donnelly	Priority noxious weed	Removal
153	Donnelly	Priority noxious weed	Removal
115	Fittler	Damage to driveway	Removal

8	Freeman	Dead	Removal
9	Freemen	Illegal Planting	Removal
29	Garibaldi	Dead	Removal
79	Glen innes	root crown	Removal
37	Gordon	Line of site	Removal
15	Garibaldi -in Allingham	reduce prune branches	Prune/deadwood
37	Gordon	Line of site	Removal
37	Gordon	Line of site	Removal
37	Gordon	Dead Tree	Removal
5	Grantham	Dying	Removal
	Green Lane	Dieback in branch	Reduce prune branch
	Kellys Plains Rd (behind 11 Erin ct)	Dead	Removal
	Kellys Plains Rd (behind 11 Erin ct)	Deadwood/ branch loading	Branch removal
184	Kentucky	Deadwood/ branch loading	Removal
184	Kentucky	Deadwood/ branch loading	Removal
139	Kirkwood	Shear crack/ TPZ compromised	Removal
295	Mann	Dead/dying	Removal
220	Mann	Dead/dying	Removal
134	Markham	dual leader dead	Remove dead leader
203	Marsh	Root crown rot	Removal
25	Mayfield	Lifting curb,road surface	Removal
	Murray		Reduction prune & remove leader
7	Niagara	poor structure and rot	Removal
103	Odell	Dying	Removal
	Ross (behind 25 Lonsdale)	Deadwood/ Dying	Dead wooding /removal
62	Rusden	Dying	Removal
175	Rusden	Remove dead wood	Dead wooding /removal
175	Rusden	Remove dead wood	Dead wooding /removal
175	Rusden	Remove dead wood	Dead wooding /removal
175	Rusden	Remove dead wood	Dead wooding /removal
27	O'Dell	unbalanced /illegal planting	Removal
175	Rusden	Remove dead wood	Dead wooding /removal
175	Rusden	Remove dead wood	Dead wooding /removal

3	Stace	Illegal planting	Removal
3	Stace	Illegal planting	Removal
2	Sylvia	Dying	Removal
1	Sylvia	Dying	Removal
1	Sylvia	Dying	Removal
1	Sylvia	Dying	Removal
1	Sylvia	Dying	Removal
40	Uralla rd	Deadwood/dying	Removal
81-85	Perrot	Dead dying	Removal
45	Ohio	Decay	Removal
45	Ohio	Decay	Removal
12	Stephen	unbalanced / EL lopping	Removal
22	McBean Ave	Dying	Removal
200	Falconer	broken hanging branches	Remove broken branches
79	Galloway	decline/roots cut - trunk decay	Removal
	Guyra Rd (opposite 7421 Guyra road)	Dead	Removal
70	Llangothlin Rd	Trunk rotted out	Removal
121	Malpas	> 60% crown loss/deadwood	Removal
	Opposite 17 Prisk	Dead/dying	Removal
	Opposite 15 Prisk	Dead	Removal
	Opposite 9 Prisk	Dead	Removal
	Opposite 9 Prisk	Excessive lean > 20 degrees	Removal
225	Sandon	Dead	Removal
	Wirruna (in roundabout)	Dead	Removal